(X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 C B. WING HAL065032 04/14/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **2744 S 17TH STREET** PACIFICA SENIOR LIVING WILMINGTON WILMINGTON, NC 28412 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 000 Initial Comments C 000 Report of a Biennial Survey by Billy S. Bryant and Greg Cates conducted on 04/14/2015. Records indicate this facility was first licensed or submitted for licensure on 06/25/1997 as a HA. The facility is currently licensed for 101 Beds with a 44 Bed Special Care Unit. Therefore the facility was surveyed for conformance with the applicable portions of the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds and applicable portions of the 1996 (1997 Revision) Edition of the North Carolina Building Code(s), Institutional Occupancy and the 1996 Rules for Licensing of Adult Care Homes of Seven or More Beds in effect at the time of initial licensure. C 101 Existing Licensed Fac- No less than '71 Rules C 101 SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction. change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation, 701 Barbour Drive, Raleigh, North Carolina, 27603 at no cost;

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

-	STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:					(X3) DATE COMF	SURVEY PLETED
							C
 		HAL06	5032	B. WING		04/	14/2015
NAME OF	PROVIDER OR SUPPLIER				STATE, ZIP CODE		
PACIFIC	A SENIOR LIVING WI	LMINGTON		TH STREET TON, NC 28			
(X4) ID PREFIX TAG	FIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL				PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROPRIES OF T	ULD BE	(X5) COMPLETE DATE
C 101	Continued From partial This Rule is not man A. Based on intervifacility was not mee operation of special Code. This could efacility if exit doors release to open durelectronic devices a locate, identify or different the manual emergence release the magnet Findings from 04/1. S.C.U The emmagnetic locked downs not carried by and some staff merpossessed the key. 2. The key for the enot identified on a keys. 3. The central emergent doors with magnetic doors with magnetic doors with magnetic lock for the determined if the seknew the combinate the key. B. Based on interviews a hazard pose locking. The emergency overlocking. The emergency magnetic door lock	et as evidence ews and obseting the required locking per ndanger any with magnetic et o failure of and staff were id not possess ency override tic locks. 4/2015: ergency release or was key of each of the dimbers were researched in the each of the dimbers were researched in the combination of operate the estimation of the estimation o	ervation the direments and the the N.C. Building occupants in the colocks did not relays or elements and the the number of the sees witch at each operated. A key direct care staff not aware of who everride switch was not aware of who werride switch for the sees witch at each operated.	C 101			

Division of Health Service Regulation

STATE FORM 6899 QVV121 If continuation sheet 2 of 13

(X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 C B. WING _ HAL065032 04/14/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **2744 S 17TH STREET** PACIFICA SENIOR LIVING WILMINGTON WILMINGTON, NC 28412 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 101 Continued From page 2 C 101 on/off only. Re-energizing the magnetic door lock by any action that is not meant to relock the door until after an emergency situation has ended is not in compliance with special locking requirements. This could endanger occupants of the facility if a magnetic lock would re-energize. the door closed and locked during an emergency requiring the door to remain open. Findings on 04/14/2015 1. The emergency override device at each exit door was key operated. In order to release the lock, a key had to be inserted into the switch, turned and held in that position. The key could not be removed so that the door would remain unlocked. This is not in accordance with the building code requirement that the emergency switch at the door operate as on/off switch. C 148 Corridors-Handrails C 148 SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL **ENVIRONMENT** (g) The requirements for corridors are: (2) Handrails shall be provided on both sides of corridors at 36 inches above the floor and be capable of supporting a 250 pound concentrated load: This Rule is not met as evidenced by: A. Based on observation the facility failed to meet the requirements for handrails in the corridor. Residents requiring the use of handrails for mobility support and assistance would be affected by not having handrails installed. Finding from 04/14/2015:

6899

STATEMEN	IT OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPL A. BUILDING:	E CONSTRUCTION 01	(X3) DATE SURVEY COMPLETED	
	HAL065032		B. WING		C 04/14/2015	
NAME OF I			l		04/1	4/2015
	PROVIDER OR SUPPLIER	2744 S 17	TH STREET	STATE, ZIP CODE		
PACIFICA	A SENIOR LIVING WI	I MINGTON	TON, NC 28			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	.D BE	(X5) COMPLETE DATE
C 148	Continued From pa	ige 3	C 148			
	installed along an a	- There is no handrail approximately 15'-0" section of at is window lined opposite the				
C 164	Housekeeping and	Furnishings-Clean, Repaired	C 164			
	FURNISHINGS (a) Adult care home (1) have walls, ceil coverings kept clea (2) have no chronic (3) have furniture of	06 HOUSEKEEPING AND				
		vation the facility has failed to repair; there is damage to				
		4/2015: s an approximately 2"x8" hole ne entrance door to the				
		er room has two holes in the tely 18"x18" hole and an " hole.				
		vation the facility failed to keep an and in good repair.				
		4/2015: dry - The flooring behind the s has accumulated dirt, lint and				

6899

	STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA			(X2) MUII TIPI	E CONSTRUCTION	(X3) DATE	SLIDVEV	
	OF CORRECTION		ATION NUMBER:	` '			(X3) DATE SURVEY COMPLETED	
				A. BUILDING:	VI			
				B. WING		С		
		HAL06	5032	D. WING		04/1	4/2015	
NAME OF I	PROVIDER OR SUPPLIER		STREET AD	DRESS, CITY, S	STATE, ZIP CODE			
DACIEIC	A SENIOR LIVING WIL	MINGTON	2744 S 17	TH STREET				
PACIFIC	A SENIOR LIVING WIL	IMINGTON	WILMING	TON, NC 28	412			
(X4) ID PREFIX TAG	SUMMARY STA (EACH DEFICIENCY REGULATORY OR LS		CEDED BY FULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROPERTION OF T	D BE	(X5) COMPLETE DATE	
C 164	Continued From pa	ge 4		C 164				
	2. Loading Dock - T the doors to the loa uneven.							
	3. 2nd Floor Unisex stains from leaking the sink.							
	C. Based on observation the facility failed to keep plumbing fixtures in good repair.							
	Findings from 04/14/2015: 1. 2nd Floor Unisex Bathroom - The lever handle is missing from the sink faucet.							
	2. Room #145 - Th and detaching from		t the toilet is loose					
C 166	Housekeeping-Mair	ntained Free	of Hazards	C 166				
	SECTION .0300 - F 10A NCAC 13F .030 FURNISHINGS (a) Adult care home	06 HOUSE es shall:	EKEEPING AND					
	(5) be maintained i orderly manner, free hazards;(e) This Rule shall	e of all obstr	uctions and					
	facilities.		and have					
	This Rule is not me A. Based on observevidenced by the fa to fire safety equipn	ation a haza ilure to main	rd was present as					
	Finding from 04/14/ 1. The control that a suppression system	activates the						

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULTIPL A. BUILDING:	E CONSTRUCTION		(X3) DATE SURVEY COMPLETED		
			A. BOILBING.			С	
		HAL065032	B. WING			4/2015	
NAME OF I	PROVIDER OR SUPPLIER	STREET AI	DDRESS, CITY, S	STATE, ZIP CODE			
PACIFIC	A SENIOR LIVING WI	I MINGTON	7TH STREET STON, NC 28				
(X4) ID PREFIX TAG	(EACH DEFICIENCY	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPF DEFICIENCY)	ULD BE	(X5) COMPLETE DATE	
C 166	Continued From pa	age 5	C 166				
	control.	nes and ready access to the nile the surveyor was on site.					
	maintain the facility	vation there was a failure to refere from a hazard. The staff in the kitchen.					
	hasp type hardware room side of the do	or from the dining room had e with a pad lock on the dining					
	hardware with a pa	oler door had hasp type d lock. d lock removed while surveyor					
	maintain the facility egress was obstruct egress would pose	vation there was a failure to ree from a hazard, a path of cted. Obstruction of the path of a hazard to facility occupants vacuate the building.					
	two 30 gallon trash Note: The trash car	/2015: air landing was obstructed by cans stored on the landing. ns were moved to a proper urveyor was on site.					
	manner. There is a	e to keep the facility in a clean pattern of HVAC ceiling grilles n as exhibited by the specific low:					
		4/2015: Cottage Hall - The return air tion damper above the grill is					

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01		(X3) DATE SURVEY COMPLETED		
	HAL065032		B. WING			C 04/14/2015	
NAME OF I	PROVIDER OR SUPPLIER	STREET ADI	DRESS, CITY, S	STATE, ZIP CODE			
PACIFIC	A SENIOR LIVING WI	I MINGTON	TH STREET TON, NC 28				
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	JLD BE	(X5) COMPLETE DATE	
C 166	Continued From pa	ige 6	C 166				
	clogged with dust.						
		Linen Room - The return air ion damper above the grille ast.					
	3. The grilles for ce bathrooms are clog	illing exhaust fans in resident ged with dust.					
		iling grilles for the HVAC nd have a layer of grease					
		vation proper operation of was not maintained.					
	Findings from 04/14/2015: 1. The ice machine condensate drain was not piped to the floor drain and was flowing water directly onto the kitchen floor.						
	Fased on observati	on the facility was not electrical hazards.					
	Multi-plug adapters	4/2015 #117 and Room #131 - without overload protection duplex wall electrical outlets.					
C 175	Bedroom Furnishin	gs-Clean Towel, Towel Bar	C 175				
	FURNISHINGS (b) Each bedroom sturnishings in good resident: (7) individual clear	PHYSICAL PLANT 06 HOUSEKEEPING AND shall have the following repair and clean for each towel, wash cloth and towel or an adjoining bathroom; and					

Division of Health Service Regulation

STATE FORM 6899 QVV121 If continuation sheet 7 of 13

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULTIPL A. BUILDING:	E CONSTRUCTION 01	(X3) DATE SURVEY COMPLETED			
	HAL065032		B. WING		C 04/14/2015		
NAME OF I	PROVIDER OR SUPPLIER		STREET AD	DRESS, CITY, S	STATE, ZIP CODE		
PACIFIC	A SENIOR LIVING WII	MINGTON	_	TH STREET TON, NC 28			
(X4) ID PREFIX TAG	SUMMARY STA (EACH DEFICIENCY REGULATORY OR L		DED BY FULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROF DEFICIENCY)	D BE	(X5) COMPLETE DATE
C 175	Continued From pa	ge 7		C 175			
	(e) This Rule shall facilities.	apply to new a	and existing				
	This Rule is not me A. Based on observ were not supplied for	ation sufficien	t furnishings				
	Finding from 04/14/ 1. There was a patt towel racks in resid specific location is I	ern of damage ent rooms, as					
	a. Room #222 - There are two residents occupying the room but only one towel rack is installed.						
	b. Several resident racks or had towel I due to missing or d	racks that were	e not useable				
C 188	Electrical Outlets in	Wet Location	S	C 188			
	SECTION .0300 - F 10A NCAC 13F .03 All adult care home locations at sinks, b building shall have	10 ELECTR electrical outlo athrooms and	ICAL OUTLETS ets in wet outside of				
	This Rule is not me A. Based on observ have the protection interrupters.	ation the wet l	ocations do not				
	Findings from 04/14 1. Kitchen - The GF kitchen did not trip v	CI electrical o	utlets in the				
	2. Room # 145 - Th	e GFCI electri	cal outlet in the				

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULTIPL A. BUILDING:	E CONSTRUCTION 01	(X3) DATE SURVEY COMPLETED			
		HAL0650	32	B. WING			C 1 4/2015
NAME OF	PROVIDER OR SUPPLIER		STREET AD	DRESS, CITY, S	STATE, ZIP CODE		
PACIFIC	A SENIOR LIVING WIL	MINGTON	_	TH STREET TON, NC 28			
(X4) ID PREFIX TAG				ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	D BE	(X5) COMPLETE DATE
C 188	Continued From pa	ge 8		C 188			
	resident bathroom	did not trip whe	n tested.				
C 189	Building Equipment	Maintained Sa	afe, Operating	C 189			
	SECTION .0300 - F 10A NCAC 13F .03 REQUIREMENTS (a) The building an mechanical, and plu care home shall be operating condition. (k) This Rule shall facilities with the ex which shall not app	d all fire safety umbing equipm maintained in apply to new a ception of Para	, electrical, lent in an adult a safe and agraph (e)				
	This Rule is not me A. Based on observe equipment is not me condition. Doors the open devices when do completely close passage of smoke occupants if smoke the room of origin.	ration, the fire saintained in an at do not release the fire alarm is and latch to recould effect all	safety operating se from hold is activated or esist the facility				
	Findings from 04/14 1. 2nd Floor Cottag hardware is not funcould not latch whe	e Hall - The pa ctioning proper					
	2. 2nd Floor Legacy doors to the corrido magnetic hold oper was activated. Whe doors did not comp	r did not releas devices when n manually ope	se from the the fire alarm erated the				
	3. 2nd Floor Large doors to the corrido						

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01			(X3) DATE SURVEY COMPLETED		
		HAL06	5032	B. WING			C 14/2015
NAME OF I	PROVIDER OR SUPPLIER	IIALOO		DRESS CITY S	STATE, ZIP CODE	0-7/	14/2013
		MINICTON		TH STREET			
PACIFIC	A SENIOR LIVING WI	LIVINGTON	WILMING	TON, NC 28	412		
(X4) ID PREFIX TAG	SUMMARY STA (EACH DEFICIENC' REGULATORY OR L		EDED BY FULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORI (EACH CORRECTIVE ACTION S CROSS-REFERENCED TO THE A DEFICIENCY)	SHOULD BE	(X5) COMPLETE DATE
C 189	Continued From pa	ige 9		C 189			
	magnetic hold oper was activated.	n devices whe	en the fire alarm				
	4. 2nd Floor Comm jammed under the closed. Note: Corrected wh	door and the	door could not be				
	5. Corridor - The fire resistant rated pair of corridor doors at exit lights #34 and #35 do not completely close and latch when released upon activation of the fire alarm system.						
	6. Room #240 - Th door hardware was latch bolt in and the	disabled with	tape holding the				
	7. Loading Dock - Toorridor do not com						
	B. Based on observation, the fire safety equipment is not maintained in an operating manner. The fire resistance of fire resistant rated doors is compromised when they are damaged or are missing required hardware or components. All facility occupants could be affected if fire resistant rated doors do not function as required to resist the spread of fire and smoke.						
	Findings from 04/14 1. Boiler Room - The automatic closer has automatic closer or does not function.	ne scissor arn as been remo	ved so the				
	C. Based on obser- components of the safe manner. The i required to be be fi compromised by the	facility are no ntegrity of cor re resistant ra	ot maintained in a nstruction ated is				

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULTIPL A. BUILDING:	E CONSTRUCTION	(X3) DATE SURVEY COMPLETED			
			7t. Boilebiito.	•		С	
		HAL065032	B. WING			4/2015	
NAME OF I	PROVIDER OR SUPPLIER	STREET A	ODRESS, CITY, S	STATE, ZIP CODE			
PACIFIC	A SENIOR LIVING WI	I MINGTON	7TH STREET STON, NC 28				
(X4) ID PREFIX TAG	(EACH DEFICIENC)	MARY STATEMENT OF DEFICIENCIES EFICIENCY MUST BE PRECEDED BY FULL ORY OR LSC IDENTIFYING INFORMATION) TAG PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)				(X5) COMPLETE DATE	
C 189	Continued From pa	nge 10	C 189				
	in the construction. could be affected if	All occupants of the facility the fire resistant rated t limit the spread of fire due to					
	rated ceiling assemescutcheons are no	5/2015 n of holes in the fire resistant ably where the fire sprinkler ot installed for the sprinkler by the specific examples					
	a. 2nd Floor -Room b. Community Room c. 2nd Floor Room d. 2nd Activity Direc e. The kitchen stora f. The kitchen Janit g. The kitchen freez	m ı #203 ctor's office. age room orial closet					
		panel is delaminating from one tant rated pair of corridor #34 and #35.					
	gap in the fire resis	are Storage Room - There is a tant rated wall where it is thes dryer exhaust duct.	1				
		damper where for the duct separating the electrical room quipment room.					
	equipment is not m condition. Illuminate not function proper occupants in the every evacuation of the factorial properties.	•					
	Findings from 04/1	5/2015					

6899

DIVISION	of Health Service Re	guiation		ı		T	
	IT OF DEFICIENCIES		R/SUPPLIER/CLIA	(X2) MULTIPL	E CONSTRUCTION	(X3) DATE SURVEY	
AND PLAN	OF CORRECTION	IDENTIFIC/	ATION NUMBER:	A. BUILDING:	01	COMPLETED	
						C	·
		HAL06	5032	B. WING		04/14/2015	
		I IALUG				<u> </u> ∪4/1	7/2013
NAME OF F	PROVIDER OR SUPPLIER		STREET AD	DRESS, CITY, S	STATE, ZIP CODE		
DACIEIC	A SENIOR LIVING WII	MINICTON	2744 S 17	TH STREET			
PACIFICA	A SENIOR LIVING WIL	- IVIIING I ON	WILMING	TON, NC 28	412		
(X4) ID	SUMMARY STA	TEMENT OF DEF	ICIENCIES	ID	PROVIDER'S PLAN OF CORRECTION	ON	(X5)
PREFIX	(EACH DEFICIENCY			PREFIX	(EACH CORRECTIVE ACTION SHOUL		COMPLETE DATE
TAG	REGULATORY OR L	SC IDENTIFTING	INFORMATION)	TAG	CROSS-REFERENCED TO THE APPROF DEFICIENCY)	RIAIE	DAIL
					·		
C 189	Continued From pa	ge 11		C 189			
	1. There is a patteri	n of Illuminate	ed directional exit				
	signs that do not ful						
	power as exhibited						
	listed below:	,	·				
	a. 2nd Floor - Smal	l Memory Car	re Unit - At the				
	nurses' station	i womery ca	TO OTHE THE HID				
	b. 2nd Floor - At the	e entrance to	the Large				
	Memory Care unit.						
	c. 2nd Floor - Comr	nunity Room	above both				
	doors to corridor.						
	C Decedes about	estion the en	ana ana sa limbina				
	E. Based on observ						
	equipment is not ma						
	Emergency lighting function properly co						
	by failing to provide						
	emergency.	marrination	in the event of an				
	omorgonoy.						
	Findings from 04/15	5/2015					
	1. There is a pattern		nted emergency				
	lights that do not fur	nction when t	ested on battery				
	power as exhibited	by some spe	cific examples				
	listed below:						
	a. 1st Floor - The fo						
	emergency corridor						
	tested on battery po	wei, #27, #2	o, #29, and #60				
	h 2nd Floor - The f	ollowing wall	mounted				
	b. 2nd Floor - The following wall mounted emergency corridor lights did not work when						
	tested on battery po						
	room off of the kitch		z zna mo otorago				
	F. Based on observ	vation, fire co	ntrol equipment				
	is not maintained in	a safe mann	er by being				
	inspected as require						
	is not inspected on	a regular bas	sis could be a				

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:					SURVEY PLETED			
		HAL065	5032	B. WING			C 1 4/2015	
	PROVIDER OR SUPPLIER A SENIOR LIVING WII	_MINGTON	2744 S 17	DRESS, CITY, S TH STREET TON, NC 28				
(X4) ID PREFIX TAG	SUMMARY STA (EACH DEFICIENCY REGULATORY OR L		EDED BY FULL	ID PREFIX TAG	PREFIX (EACH CORRECTIVE ACTION SHOULD BE			
C 189	Continued From padanger to occupant of a fire the equipm limit the fire due to Finding from 04/15/1. There was no do fire extinguishers hamonthly basis prior G. Based on observation of the part of the fadequipment could occupants of the fadequipment could accupant the double doors unit did not activate	s of the facility ent could not malfunction. 2015 cumentation and been inspect to 04/2015. Vation, a fire and dition. Fire all dition the all and the fire to the Small	that the portable ected on a alarm devices that ger to all event of a fire the rm system due to alarm pull station Memory Care	C 189				

6899